



1001 Trout Brook Crossing  
Rocky Hill, CT 06067-3910  
Telephone: (860) 571-5100  
FAX: (860) 571-5465

## Product Description Sheet

### FREKOTE<sup>®</sup> HMT-2 Mold Release Agent

Industrial Products, October 2003

#### Description

Loctite<sup>®</sup> Frekote<sup>®</sup> HMT-2 is a hot mold touch up version of Frekote 55-NC and is formulated for use on molds with temperatures above 60°C (140°F). After one touch up coat, HMT-2 continues to offer the same multiple releases per application as experienced with the other Frekote products. For constant mold temperatures over 60°C (140°F), Frekote HMT-2 performs effectively on its own.

#### Features

Multiple Release  
No contaminating transfer  
No mold build up  
Minimum reject rates  
Low odor  
High temperature application

#### Properties

Appearance	Clear Liquid
Odor	Aliphatic Hydrocarbon
Solvents	Aliphatic Hydrocarbons
Specific Gravity	0.770 +/- 0.015
Shelf Life	One year from date of manufacture
Special Cautions	Moisture sensitive, keep container tightly closed when not in use.
Cured thermal stability	400°C (750°F)
Application Temp	60°C - 190°C (140°F -375°F)

#### Mold Preparation

The mold surface must be clean and free of any non-Frekote release agents or other contaminants for Frekote HMT-2 to be completely effective. Remove any contaminants with Frekote PMC or other suitable cleaning solvents. Light industrial abrasives can be used to remove heavy resin build up. No mold preparation is required when HMT-2 is used as a touch up coat over another Frekote Product.

#### Application \*Consult MSDS prior to use\*

Frekote HMT-2 is intended as a touch up on mold surfaces above 60°C (140°F) and applied by spraying or brushing. For spraying use conventional equipment, ensuring a dry air source or an airless spray system. Frekote HMT-2 dries very rapidly at elevated temperatures. Care should be taken to ensure complete coverage.

#### Touch-up

Spray or brush on one thin wet film coating over the entire mold surface or on the area that is experiencing difficult release. Allow time for complete solvent evaporation. Upon drying, the HMT-2 polymer is cured and ready for production.

#### Constant Use

1. If using Frekote HMT-2 as a releasing system on its own, apply a thin wet continuous film coating the entire mold. It is suggested that small areas be coated working progressively from one side of the mold to the other.

2. For the initial application 4 – 6 coats are recommended, allowing a few minutes between coats for solvent evaporation.
3. After the final coat, curing is completed through solvent evaporation and ready for production.
4. Maximum releases will be obtained as the mold surface becomes conditioned to Frekote HMT-2. Performance is enhanced by re-coating once, after the first few initial moldings.

#### Flammability/Storage

Frekote HMT-2 contains flammable solvents. The product should always be used in well-ventilated areas. Store in a cool dry place. Consult MSDS for complete details.

#### Note

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Loctite Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Loctite Corporation's products. Loctite Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.** The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Loctite Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more, United States, or foreign patents or patent applications.

NOT FOR PRODUCT SPECIFICATIONS

THE TECHNICAL DATA CONTAINED HEREIN ARE INTENDED AS REFERENCE ONLY.

PLEASE CONTACT LOCTITE CORPORATION QUALITY DEPARTMENT FOR ASSISTANCE AND RECOMMENDATIONS ON SPECIFICATIONS FOR THIS PRODUCT.  
ROCKY HILL, CT FAX: +1 (860)-571-5473 DUBLIN, IRELAND FAX: +353-(1)-451 - 9959

Loctite and Frekote are Registered Trademarks of Loctite Corporation U.S.A.